DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-024883 Address: 333 Burma Road **Date Inspected:** 11-Jun-2011

City: Oakland, CA 94607

Project Name: SAS Superstructure **OSM Arrival Time:** 700 **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes An Qing Xiang No Yes N/A **Rod Oven in Use:** Yes **Inspected CWI report:** No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes N/A **Delayed / Cancelled:** No

Bridge No: 34-0006 **Component:** OBG

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance (QA) Inspector Umesh Gaikwad was present during the times noted above for observations relative to the fabrication of the Self-Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

TA YARD, OBG 14W (NWIT # 09430)

This QA Inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA inspector generated MT report for this date. The members are identified as OBG Components. The weld designations reviewed are as follows.

SEG3020T-244~255, 324, 325

SEG3020W-057, 059, 149, 154, 159, 164, 169, 174

SEG3020R-102, 103, 107, 108, 112, 113, 117, 118, 122, 123, 127, 128, 099, 104, 109, 114, 119, 124

TA YARD, OBG 14W (NWIT # 09433)

This QA Inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA inspector generated MT report for this date. The members are identified as OBG Components. The weld designations reviewed are as follows.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

SEG3020M-082~085, 140~143, 146~149, 152~155, 158~161, 164~167, 170~173, 176~179, 182~185 SEG3020K-325, 329, 333, 337, 341, 345, 349, 353, 357

This Quality Assurance (QA) Inspector observed the following work in progress:

TA YARD

OBG Seg 14W:

The Shielded Metal Arc Welding (SMAW) process on weld joint no: SEG3020V-034 [Complete Joint Penetration (CJP) weld at panel point (PP) 125]. The welders are identified as 066479 & 066261 and were observed welding in 2G position. ZPMC QC was identified as Mr. An Qing Xiang. The welding variables recorded by this QC appeared to comply with WPS: B-P-2212-Tc-U4b-FCM-1.

The SMAW process on weld joint no: SEG3020V-029 [CJP weld at panel point (PP) 125]. The welder is identified as 066002 and was observed welding in 2G position. ZPMC QC was identified as Mr. An Qing Xiang. The welding variables recorded by this QC appeared to comply with WPS: B-P-2212-Tc-U4b-FCM-1.

The SMAW process on weld joint no: SEG3020V-027 [CJP weld at panel point (PP) 125]. The welders are identified as 067520 & 066019 and were observed welding in 2G position. ZPMC QC was identified as Mr. An Qing Xiang. The welding variables recorded by this QC appeared to comply with WPS: B-P-2212-Tc-U4b-FCM-1.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang: 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Gaikwad,Umesh	Quality Assurance Inspector
Reviewed By:	Peterson,Art	QA Reviewer